Sound Control Technologies

RC8 Gen2 Firmware Release

V3.0 - 11/14/2025
Update Time: 9 minutes

Files included in this release:
RC8 Gen2 HE
680_1071_02 RC8 Gen2 HE Application FW Version: 00.01.20
671_1071_01 RC8 Gen2 HE Valens UPT Version (Bank1): 7.005.028
672_1071_01 RC8 Gen2 HE Valens Base Image Version (Bank 3): 7.005.027
673_1071_01 RC8 Gen2 HE Valens Base Image Version (Bank 4): 7.005.027
Bank 0: No update

RC8 Gen2 CE
671_1072_01 RC8 Gen2 CE Valens UPT Version (Bank1): 7.005.028
672_1072_01 RC8 Gen2 CE Valens Base Image Version (Bank 3): 7.005.027
673_1072_01 RC8 Gen2 CE Valens Base Image Version (Bank 4): 7.005.027
Bank 0: No update

Release notes:

1. Improved wake-up time when coming out of Cisco Standby/Sleep mode.

V2.0 - 9/08/2025: Initial public release.
Update Time: 9 minutes

Files included in this release:
RC8 Gen2 HE
680_1071_02 RC8 Gen2 HE Application FW Version: 00.01.10
671_1071_01 RC8 Gen2 HE Valens UPT Version (Bank1): 7.005.026
672_1071_01 RC8 Gen2 HE Valens Base Image Version (Bank 3): 7.005.026
673_1071_01 RC8 Gen2 HE Valens Base Image Version (Bank 4): 7.005.026
Bank 0: No update

RC8 Gen2 CE
671_1072_01 RC8 Gen2 CE Valens UPT Version (Bank1): 7.005.026
672_1072_01 RC8 Gen2 CE Valens Base Image Version (Bank 3): 7.005.026
673_1072_01 RC8 Gen2 CE Valens Base Image Version (Bank 4): 7.005.026
Bank 0: No update