

Sound Control Technologies

RCU2E Firmware Release

V3.0 – 4/14/2025:

Included Files:

602_1020_02 RCU2E-HE Application FW Version: 00.12

670_1020_02 RCU2E-HE Valens FW Versions: 2.200.14 main (bank 1), 2.200.111 or 2.200.211 configuration (bank 2)

680_1019_02 RCU2S-CE Application FW Version: 00.05

671_1019_02 RCU2S-CE Valens FW Version: 2.200.14 main (bank 1), 2.200.111 or 2.200.211 configuration (bank 2)

Release notes:

1. Improved Ethernet auto-negotiation.
2. Resolved IP connection issues with AVer cameras.

V2.0 – 3/27/2025:

Included Files:

602_1020_01 RCU2E-HE Application FW Version: 00.11

670_1020_02 RCU2E-HE Valens FW Versions: 2.200.14 main (bank 1), 2.200.111 or 2.200.211 configuration (bank 2)

680_1019_01 RCU2S-CE Application FW Version: 00.04

671_1019_02 RCU2S-CE Valens FW Version: 2.200.14 main (bank 1), 2.200.111 or 2.200.211 configuration (bank 2)

Release notes:

3. Added USB Vendor ID, Product ID, and USB Descriptors.
4. Resolved connection issues with Poly Lens Desktop and G9+ Room Controls not working with E60 and E70 cameras.

v1.0 - 6/26/2023: Initial public release.