

Sound Control Technologies

RCU3SL Firmware Release

V2.0 - 2/13/2026

Files included in this release:

680_1060_01 RCU3SL-HE MCU Application FW Version: 00.01.15
670_1060_01 RCU3SL-HE Valens Firmware Version (Bank 1): 1.002.010
671_1060_01 RCU3SL-HE Valens Firmware Version (Bank 2): 1.002.106

680_1061_02 RCU3SL-CE MCU Application FW Version: 00.01.10
670_1061_01 RCU3SL-CEValens Firmware Version (Bank 1): 1.002.010
671_1061_01 RCU3SL-CE Valens Firmware Version (Bank 2): 1.002.106

Release notes:

1. Fixed incompatibilities with Poly X32, X52, X72, and E70 cameras.
2. Added ability to disable Power Delivery (PD) with DIP switch 4.

v1.0 - 4/21/2025: Initial public release.

Files included in this release:

680_1060_01 RCU3SL-HE MCU Application FW Version: 00.01.15
670_1060_01 RCU3SL-HE Valens Firmware Version (Bank 1): 1.002.010
671_1060_01 RCU3SL-HE Valens Firmware Version (Bank 2): 1.002.106

680_1061_01 RCU3SL-CE MCU Application FW Version: 00.01.00
670_1061_01 RCU3SL-CEValens Firmware Version (Bank 1): 1.002.010
671_1061_01 RCU3SL-CE Valens Firmware Version (Bank 2): 1.002.106